## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,052,636 B2 Page 1 of 2

APPLICATION NO. : 10/619048 DATED : May 30, 2006

INVENTOR(S) : Ausen, Ronald W. et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title Page, Item (57) (Abstract) – Line 9 - Delete "cross sectional" and insert - - cross-sectional - -, therefor.

Column 2 – Line 37 - Delete "82 m" and insert –  $\mu$ m – -, therefor.

Column 2 - Line 60 - Delete "cross sectional" and insert - - cross-sectional - -, therefor.

Column 3 – Line 36 - After "invention" delete ";" and insert - - . - -, therefor.

Column 4 – Line 61-62 - Delete "cross sectional" and insert - - cross-sectional - -, therefor.

Column 6 - Line 7 (Approx.) - Delete "21" and insert - - 21' - -, therefor.

Column 7 – Line 10 - Delete "due" and insert - - due to - -, therefor.

Column 8 - Line 58 - After "thereof" insert - - . - -.

Column 15 – Line 54 (Approx.) - Delete "B' (random)[i]=intensity value of minimum in oscillatory pattern" and insert - B' (random)[i]=intensity value of minimum in oscillatory pattern - -, therefor.

Column 21 – Line 55 - Delete "Thicknesses" and insert - The thicknesses - -, therefor.

Column 23 – Line 7 - Delete "TiO<sub>2</sub>" and insert - - TiO<sub>2</sub> - -, therefor.

Column 24 Table 6 Col. 3 – Line 4 - Delete "(µm" and insert - - (µm) - -, therefor.

Column 25 Table 6-Continued Col. 3 – Line 4 - Delete " $(\mu m)$ " and insert - -  $(\mu m)$  - -, therefor.

Column 26 – Line 6 - delete "skunk" and insert - - shrunk - -, therefor.

Page 2 Missing